

#### UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

REGION 4
ATLANTA FEDERAL CENTER
61 FORSYTH STREET
ATLANTA, GEORGIA 30303-8960

OCT 17 2013

Mr. Michael Clements AEI Consultants, Inc. 6065 Roswell Road, Suite 940 Atlanta, Georgia 30328

RE: Freedom of Information Request No. EPA-R4-2013-009413

Dear Mr. Clements:

This letter is in response to your Freedom of Information Act (FOIA) request dated August 26, 2013, pertaining to environmental records for soil, groundwater and CERCLIS-NFRAP investigations of the Crown Central Petroleum Corporation located in Doraville, Georgia.

Please find enclosed a copy of report #GAD079362661 for Crown Central Petroleum Corp., which is responsive to your request. Fees are waived as <u>de minimis</u>.

If you have any questions regarding this response, please contact Urshula Swann, FOIA Specialist, at (404) 562-8179 or <a href="mailto:swann.urshula@epa.gov">swann.urshula@epa.gov</a>.

Sincerely,

LouAnn Gross, Chief

Information Access Section

Enclosure

SITE DATA

U. S. ENVIRONMENTAL PROTECTION AGENCY OFFICE OF EMERGENCY AND REMEDIAL RESPONSE DATA BASE UPDATED 85/01/33
T.1 - ERRIS TURNAROUND DOCUMENT

0 SHEET EPA ID NO.: GAD079362661

SOURCE COUNTS: COMPOSITE: COST RECOV. \* \* OTHER: HADMS: NOTIS: STS: 40 z ENF. RESP. \* \* CONG. DIST: SOURCE: ZIP: 30340-089 CNTY CODE: NO FURTHER ACTION VOL. RESP. \*\_\* 084/16/48.0 ST: GA CROWN CENTRAL PETROLEUM CORP LONGITUDE: RESPONSE TERMINATION (CHECK ONE IF APPLICABLE): PENDING \*\_\_\* ENF. DISP. (CHECK ANY THAT APPLY): NO VIABLE RESP. PARTY \*\_\_\* 2765 WOODWIN RD 33/54/00.0 DORAVILLE (ACTION : \* \* - FOR DATA ENTRY USE ONLY) DEKALB CNTY NAME: LATITUDE: SITE NAME: STREET: CITY: HRS DATE (YY/MM): \* / \* \*| \*| NATL PRIORITY: N HRS: \* ....\* :01 S

0 0 0

> NON-SITE: FED. FAC. (Y/N): N REG. FLD2: REG. FLD1: \* RSPO PHONE: 03130001 :135 USGS HYDRO. RSPO NAME: \* 0520

\* SITE DESCRIPTION: SMSA:

EVENTS \*\*\*\*\*

COUNTS \*| EPA STATE RESP/PARTY OTHER \*| \*| \*| \*! \*| \*| \* \*| DATE (YY/NM) COMPLETED 81/06 82/09 DATE (YY/HM) STARTED -------82/09 (X) PRELIMINARY ASSESSMENT (PA) SITE INVESTIGATION (SI) REMEDIAL ACTION (RD) (X) SITE DISCOVERY (SD) REMOVAL ACTION (RV) .......... (ACTION - FOR DATA ENTRY USE ONLY) EVENT TYPE \*| \*1 \*| \*| \* RESPONSE **EVENTS** 

\*| \*| \*| \*| \*| \*| \*| \*| \*| \*| \*| ENFORCEMENT INVESTIGATION (EI) \*\_\_\_/\_\_ ADMINISTRATIVE ORDER (AO) JUDICIAL ACTION (JA) \*| \*| \*| ENFORCE. EVENTS

RUN DATE: 85/01/03 RUN TIME: 23:43:00

ļ

11

U. S. ENVIRONMENTAL PROTECTION AGENCY OFFICE OF EMERGENCY AND REMEDIAL RESPONSE DATA BASE UPDATED 85/01/03 T.1 - ERRIS TURNAROUND DOCUMENT

PAGE: 426 RUN DATE: 85/01/03 RUN TIME: 23:43:00

20 SHEET EPA ID NO.: GAD079362661

> CROWN CENTRAL PETROLEUM CORP SITE NAME:

\*ALIAS\* (ACTION \*\_\* - FOR DATA ENTRY USE CNLY)

SOURCE: ALIAS NAME: \*\_ SEQ. NO.: \* \*

\*ALIAS LOCATION\* (ACTION \*\_\* - FOR DATA ENTRY USE ONLY)

CONTIGUOUS PORTION OF SITE:

CONG. DIST.: \*\_\_\* ST: \* \* CNTY CODE: CNTY NAME: STREET: CITY:

USGS HYDRO. UNIT: SHSA: \* \* LONG.: \* \_\_/ LAT:

\*ALIAS\* (ACTION \*\_\* - FOR DATA ENTRY USE ONLY)

SOURCE: ALIAS NAME: \* SEQ. NO.: \* \*

\*ALIAS LOCATION\* (ACTION \* - FOR DATA ENTRY USE ONLY)

CONTIGUOUS PORTION OF SITE:

CONG. DIST.: \* ...\* ZIP: \*| CNTY CODE: ST: CNTY NAME: STREET: CITY:

USGS HYDRO. UNIT: SMSA: \*! LONG.: LAT:

ı

1

U. S. ENVIRONHENTAL PROTECTION AGENCY OFFICE OF EHERGENCY AND REHEDIAL RESFONSE DATA BASE UPDATED 85/01/03 T.1 - ERRIS TURNAROUND DOCUMENT

PAGE: 427 RUN DATE: 85/01/03 RUN TIME: 23:43:00

EPA ID NO.: GAD079362661 SHEET 03

SITE NAME: CROWN CENTRAL PETROLEUM CORP

SITE COPMENTS

COMMENT	GASO00001031-DISPOSAL OCCURRED AT PETROLEUM PRUDUCT TERMINAL SITE.	LEADED TANK BOTTOMS GENERATED BY THE CLEANING OF GASOLINE STORAGE	TANKS WERE DISPOSED OF ON SITE BY THE BURIAL METHOD IN ACCORDANCE WITH	STANDARD INDUSTRY PRACTICE. SEE ATTACHHENTS A AND B. 1962 TO 63.	CONTACT: PHIL B. ONDERDONK/ MARKETING ATTY. 301-539-7400.	***		*		*	*	*			**		**		*	*	*	
COMMENT	100	002	003	900	900	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	
(ACTION - FOR DATA EHTRY USE ONLY)	*  *	*	*1	*	*	*1	<u>*</u> 1	*1	*,i	*	<b>,</b>	<b>i</b> *!	*    *	*,	*,	*	*	*!	*,1	*	*	ļ ;

1'

U. S. ENVIRONMENTAL PROTECTION AGENCY OFFICE OF EMERGENCY AND REMEDIAL RESPONSE DATA BASE UPDATED 85/01/03 T.1 - ERRIS TURNAROUND DOCUMENT

PAGE: 428 RUN DATE: 85/01/03 RUN TIME: 23:43:00

40 SHEET EPA ID NO.: GAD079362661

SITE NAME: CROWN CENTRAL PETROLEUM CORP

REGIONAL ENTRIES

(ACTION - FOR DATA ENTRY USE ONLY)	ENTRY CODE	DESCRIPTION
*,	*	* * * * * * * * * * * * * * * * * * * *
*!	*	***************************************
*  *	*	*
*	*	* * * * * * * * * * * * * * * * * * * *
*	*	* * * * * * * * * * * * * * * * * * * *
*  *	*	* *************************************
*	*	* *************************************
*	*	* **-/-/-**-/-/-**
*	*	* * * * * * * * * * * * * * * * * * * *
*  *	*	* * * * * * * * * * * * * * * * * * * *
*	*	* *************************************
*1	*	* * * * / / / * * / / / * * / / / * * / / / * * / / / * * / / / / * * / / / / * * / / / / * * / / / / * * / / / / * * / / / / * * / / / / * * / / / / * * / / / / * * / / / / * * / / / / * * / / / / / * * / / / / / * * / / / / / * * / / / / / * * / / / / / * * / / / / / * * / / / / / * * / / / / / * * / / / / / * * / / / / / * * / / / / / * * / / / / / * * / / / / / * * / / / / / / * * / / / / / * * / / / / / * * / / / / / * * / / / / / * * / / / / / * / / / / / * / / / / / / / * / / / / / / / * /
*	*	* * * * * * * * * * * * * * * * * * * *
*	*	* **

Ì

1'

,	Ç,	F	F		1
	_		-	_	-

#### POTENTIAL HAZARDOUS WASTE SITE IDENTIFICATION AND PRELIMINARY ASSESSMENT

REGION SITE NUMBER (to be do-

NOTE:	This	form	is com	pleted	for ea	ch potent	ial bai	ardous	wast	e site	to help	set ;	priorities	for	site	inspect	tion.	The	informatio	<u>-</u>
submitte	d on	this f	orm ls	besed	OB 87	ulable re	cords	and may	pe a	pdeted	00 811	bsequ	seat form		. 191	sult of	additi	onal	inquiries	
and on-	ite is	speci	ions.																	

GENERAL INSTRUCTIONS: Complete Sections I and III through X as completely as possible before Section II (Preliminary

Agency; Site Tracking System; Hazar	ious Vaste Enforcement Te	sk Force (EN-	755; 401 M St., 1	W; Wash	ington, DC 20460.
	I. SITE IDE	ITIFICATION			
A. SITE HAME	4		other identifier)		
CROWN CENTRAL PETROL	EUM CORP	2/65	WOODWIN	Rb.	ITY NAME
DOTTAVILLE		GA.	30340	DEKA	· · · · · · · · · · · · · · · · · · ·
G. OWNER/OPERATOR (II MONT)					
S. NAME	ATTV			1	PHONE NUMBER
ONDERDONK, PHIL B	). 1114			301	539 7400
H. TYPE OF OWNERSHIP  1. FEDERAL 2. STATE	]3. COUNTY	IPAL HE	PRIVATE 6.	UNKNOWN	
I. SITE DESCRIPTION BUIZIAL	PIT 1962-63 For	t LEADE I	> TANK BO	T TOM S	5
J. HOW IDENTIFIED (I.e., citizen's comple	inte, OSHA citatione, etc.)				K. DATE IDENTIFIED
103 C NOTIF	ICATION				6-8-81
L. PRINCIPAL STATE CONTACT					
MOSES N. MCCA	<b>LL</b>				656-2833
	RELIMINARY ASSESSMEN	IT (complete th	us section last)	· · · · · ·	
A. APPARENT SERIOUSNESS OF PROBLE					
1. HIGH 2. MEDIUM	3. LOW A HONE	<b>□</b> s. ∪	NKHOWN		
B. RECOMMENDATION T. NO ACTION NEEDED (no heared)			IATE SITE INSPEC ATIVELY SCHEDI		
3. SITE INSPECTION NEEDED  B. TENTATIVELY SCHEDULED FO	en e	b. WILL	BE PERFORMED	BY:	* *
b. WILL BE PERFORMED BY:					A
		4. SITE !!	ISPECTION NEED!	ED (100 pr	ienty)
C. PREPARER INFORMATION					
F. NAME		2. TELEI	PHONE NUMBER	277	9-13-82
JIM USSERY			<u>-636-28</u>	777	11306
	III. SITE IN	FORMATION		<u> </u>	
A. SITE STATUS  1. ACTIVE (These industrial or municipal sites which are being used for waste treatment, sterage, or disposal on a continuing basis, even it info-quently.)	A 2. INACTIVE (Those dies which no lenger receive wester)	3. OTHER (These sites the ne regular er co	(apacify): at include such inc antinuing use of the	idonto Illia alto for w	''midnight dumping'' where aate dispeasi hae eccurred.)
B. IS GENERATOR ON SITE?	2. YES (specify gener	reter's low-digit	g(C Codo):		,
UNKNOWN	D. IF APPARENT SERIOUSNI 1. LATITUDE (dog		HIGH, SPECIFY CO		
E. ARE THERE BUILDINGS ON THE SITE  1. NO 2 YES (specify)					

Ca	ntinued From Front								<u>_</u>				•
				ΙV	. c	HARACTERIZATIO	H	OF SITE ACTIVITY	1				
In	dicate the major site	. 80	tivity(les	) and deta	ils	relating to each ac	Ú٧	ity by marking 'X' is	a U	e appropr	iate boxes	<u>.                                    </u>	
×.	A. TRANSPORT	ren	×	•	). S	TORER '	4	C. TREATER	1	·x·	0	. 0	ISPOSER
	I. RAIL			1. PILE			ŀ	, FILTRATION		X	. LANDFII	L	
	2. SMI#			2. SURFA	C &	IMPOUNDMENT	2	. INCINERATION			. LANDFA	RM	l
L	S. BARGE			3. DRUM				. VOLUME REDUCTION	ON		OPEN D	JMI	<u> </u>
	4. TRUCK			4. TANK.	A B	OVE SROUND	1	. RECYCLING/RECO	VE	^~	. SURFAC	K II	MPOUNDMENT
L	S. PIPELINE			S. TANK.	36	LOW GROUND	<u> •</u>	. CHEM./PHYS. TRE	AT	MENT	. MIDNICH	T	DUMPINE
L	6. OTHER (opecity):		<u> </u>	Je. OTHER	(4	pocify):	-	. BIOLOGICAL TREA	-		. INCINER	_	
l							+	. WASTE OIL REPRO		31M6		_	HOITSELM GHU
1			1			-	-	. SOLVENT RECOVE . OTHER (eposity):	RY		. OTHER (	-	erry):
						-							
1	SPECIFY DETAILS	OF	SITE ACT	IVITIES AS	NI	EEDED / FARER	TA	ALK BATTAMS	61	NEITAT	FD BY	_	THE CLEANING
1 4	of gasoline		STORA	6€ TA	Ní	(5 NEIZE D	15	POSED OF A	L	-SITE	BY TI	u e	BURLAL
	METHOD IN	A	COLLON	NULE II	,,-	TU STALIDAD		LINDUSTRY I	77	ALTIC	F		1 ATTE ()
F	ART OF 196	2	OTC EA	TTAM!	36	3 TANK #1	V	AS CLEANED	f	TAVO	WHEEL	3 A	MOTITAL LOADS
C	F LEADED TI	4 ~	130	1 10 713	\\\ 	TEIRE ISUITIED	'	DETWEEN TAI	~	· # 1 #	2		
						V. WASTE RELATI	Đ	INFORMATION	_				
^	. WASTE TYPE												
L	X1. UHKHOWH X	<u> </u>		•	. \$0	DLID 🛱 81	LUC	DGEL.Q.	AS				
	WASTE CHARACTER												
	<del></del>	_		_		=		IOACTIVE SH	IGH	LY VOLA	TILE		
	X)6. TOXIC	J7.	REACTIVE	E	. IN	IERT9. F	LA	MMABLE					
	10. OTHER (opecify												
С	. WASTE CATEGORIE 1. Are records of wast	3	vallablet	Specify its	-	such as manifests, in	7 04	incies, etc. below.			•		
1	No									•			
L		_		- 14 - 4									
$\vdash$	2. Estimate the amo	זמט			-		Col	<del></del>	T T			-	
	a. SLUDGE		L OII	L	A	e. SOLVENTS	4.	4. CHEMICALS	<b> </b>	e. SOL	IDS	A	f. OTHER
	MUKNOUM												
Ü	NIT OF MEASURE	UN	LOPIE	ABURE	Ü	IT OF MEASURE	v	HT OF MEASURE	Ü	IT OF ME	ASURE	5	IT OF MEASURE
ı								•			_		
×	(1) PAINT, PISMENTS	×	(1) OIL Y	ts .	×	(1) HALOGENATED	×	(1) A CIDS	×	(1) PLYAS	H	×	(1) LABORATORY PHARMACEUT.
		┢	(010====		一	(3) NON-W 11 CC1:	t	(2) PICKLING	H		_	<b> </b>	
X	(2) METALS SLUDGES	T	, GOTHE	R (apocity):		SOLVENTS	1	Liquors	L	(2) ASSES		L	U)HOSPITAL
L	(3) POTW			!	-	(3) OTHER(specify):	L	(B) CAUSTICS		MINE '	ALLINGS		(8) RADIOACTIVE
	(4) ALUMINUM SLUDSE							(4) PESTICIDES		(4) PERR	OUS . WASTES		(4) MUNICIPAL
F	(S) OTHER (Specify):	1						(8) DYES/WKS		(B) NON-F	ERROUS L. WASTES		(B) OTHER (aposity):
1	LEADED	١					T	(6) CYANIDE	L	(0) OTHE	(epocity):		
ı	schibbe						-	<del> </del>	ł			ĺ	
ı							L	(7) PHENOLS					
								(S) HATOGENS					•
						.*		(0) PC D	1				
								(10)METALS	1				
		l			1		H		1			ĺ	
						,	H	_i(11) OTHER(epocity)	1				
1					ľ				1			ı	

V. WASTE RELATED INFORMATION (continued)
3. LIST SUBSTANCES OF GREATEST CONCERN WHICH MAY BE ON THE SITE (place in descending order of hazard).

LEAD

4. ADDITIONAL COMMENTS OR NARRATIVE DESCRIPTION OF SITUATION KNOWN OR REPORTED TO EXIST AT THE SITE.

NONE

		VI. HAZ	ARD DESCRIPTI	UN
A. TYPE OF HAZARD	B. POTEN- TIAL HAZARD (mark 'X')	C. ALLEGED INCIDENT (mark 'X')	D. DATE OF INCIDENT (moday,yr.)	E. REMARKS
I. NO HAZARD				
2. HUMAN HEALTH				
NON-WORKER NJURY/EXPOSURE				
4. WORKER INJURY				
CONTAMINATION OF WATER SUPPLY				
CONTAMINATION OF FOOD CHAIN				
7. CONTAMINATION OF GROUND WATER	X			
CONTAMINATION OF SURFACE WATER				·
DAMAGE TO FLORA/FAUNA				
TO, FISH KILL				
II. CONTAMINATION OF AIR				
12. NOTICEABLE ODORS				
13. CONTAMINATION OF SOIL	X			
14. PROPERTY DAMAGE				·
IS. FIRE OR EXPLOSION				
IG. EPILLS/LEAKING CONTAINERS/ RUNOFF/STANDING LIQUIDS				
7. SEWER, STORM DRAIN PROBLEMS				·
is. EROSION PROBLEMS				
16. INADEQUATE SECURITY				
O. INCOMPATIBLE WASTES				
EL MIDNIGHT DUMPING				
2. OTHER (specify):				
•		1 1		·

Continued From Front				
			VII. PERMIT INFO	RMATION
A. INDICATE ALL APPLI	CABLE PERM	HTS HELD BY T	HE SITE.	
1. NPDES PERMIT	2. SPC	PLAN _	3. STATE PERMIT	(specify)
4. AIR PERMITS	S. LOC	AL PERMIT	6. RCRA TRANSPO	PRTER
7 RCHA STORER	E RCR	A TREATER	9 RCRA DISPOSE	<b>A</b> .
10. OTHER (apacity)	มอนธ			
B. M COMPLIANCE?		A	1	
I. YES	2. NO	7	3. UNKNOWN	
4. WITH RESPECT T	O (list regula	tion name & numb	oe)·	
		VIII.	PAST REGULATO	DRY ACTIONS
A. NONE	. B. YES	(aummarize belo	w)	
•				
•				
		IX. INSPI	CTION ACTIVITY	(past or on-going)
A NONE	■ B. YES	(complete itema )	,2,3, & 4 below,	
1 TYPE OF ACT'V	''TY	2 DATE OF PAST ACTION (mo., day, & yr.)	3 PERFORMED BY: (EPA/State)	4. DESCRIPTION
	1			
		X. RE	MEDIAL ACTIVITY	f (past or on-going)
A. NONE	☐ B. YES	(complete itema	1, 2, 3, & 4 below)	
1. TYPE OF ACTIV	VIT 4	2. DATE OF PAST ACTION (mo., day, & yr.)	3. PERFORMED BY: (EPA/State)	4. DESCRIPTION
		n in Sections page of this fo		l out the Preliminary Assessment (Section II)

EPA Form T2070-2 (10-79)

PAGE 4 OF 4

RW OX

**≎FPA** 

### POTENTIAL HAZARDOUS WASTE SITE IDENTIFICATION AND PRELIMINARY ASSESSMENT

REGION SITE NUMBER (to be as-

NOTE: This form is completed for each potential hezerdous waste site to help set priorities for site inspection. The information submitted on this form is based on available records and may be updated on subsequent forms as a result of additional inquiries and on-site inspections.

GEMERAL INSTRUCTIONS: Complete Sections I and III through X as completely as possible before Section II (Preliminary Assessment), File this form in the Regional Hazardous Waste Log File and submit a copy to: U.S. Environmental Protection Agency; Site Tracking System; Hazardous Waste Enforcement Task Force (EN-335); 401 M St., SW: Washington, DC 20460.

Agency; one incling system, nasardous waste Emore		(BIT-555), 401 M 00., 5		
		ON		
GAD079362661 DE KALB L CROWN CENTRAL PETROLEUM CORP		(or other identifier)		
C 2765 WUUDWIN RD	30340	E. ZIP CODE	TE. COUNT	TY NAME
DORAVILLE GA ONDERDONK, PHIL B. MKTG.* 30	15397400		2 TOLES	THONE NUMBER
M	I MUNICIPAL	15 PRIVATE : 6	ON NOA!	
11. \$1"				
"103-C NOTIFICATION" DATE:  JH JIM SETZER PHONE: 404-656-2833	810608			K. DATE IDENTIFIED (mo., day, & yr.)
L. F			. 7 E i. E P	PHONE NUMBER
II. PRELIMINARY ASS	ESSMENT (comple	eta this section last)	h	
A. APPARENT SERIOUSNESS OF PROBLEM  [1] 1. HIGH [1] 2. MEDIUM [3] LOW [1] 4	NONE	15 UNKNOWH		
RECOMMENDATION  1. NO ACTION NEEDED (no hexard)		MMEDIATE SITE INSPEC TENTAT VELY SCHECK		DFU
3. SITE INSPECTION NEEDED  a. TENTATIVELY SCHEDULED FOR:	b.	WILL BE PEPFORMED &	ð 'y	
b. WILL BE PERFORMED BY	[ ] 4. si	ITE INSPECTION NEEDS	in training	relly)
C. PREPARER INFORMATION S. NAME	7. 7	FLEPHONE NUMBER		3. DATE (MO., day, & yr.)
111	ITE INFORMATI	A.1.		81 01 1)
A. SITE STATUS	cee [ ]3. OT	HER (specify).	sita for whi	'midnight dumping' where sle disposal has occurred.)
B. IS GENERATOR ON SITE?  1. NO  2. YES (open	ffy generator's loui-	-digit 51¢ Code):	m. , a some at the state of	<del></del>
C. AREA OF SITE (In ecres)  D. IF AFPARENT SE		E IS HIGH, SPECIFY CO		
E. ARE THERE BUILDINGS ON THE SITE?  1. NO 2. YES (epocity):			,	

Cor	ntinued From Front								public to year				
				_	HARACTERIZATIO		,						
Ind	licate the major site	e ac	tivity(ies) and deta	ıls	relating to each ac-		ty by marking 'X' in	th	ie obb	ropr	iate hoxes	<u>.</u>	
' X '	A. TRANSPORT	TER	×	). S	STORER	×	C. TREATER			1 3		). D	ISPOSER
	1. RAIL		1 PILE			F	FILTRATION		Ì	<b>∮</b> ∳	L LANOF!		
	2. SHIP		2. SURFA	C E	IMPOUNDMENT		INCINERATION				2. LANDEA		
	3. BARGE		3. DRUMS				. VOLUME REDUCTIO				OPEN D		
LĪ	4. TPUCK		4. TANK.	A P	OVE GROUND	4	RECYCLING HECO	E	Ff 5	<b>}</b> +			MPOUNDMENT
	5. PIPELINE		S. TANK.	86	LOW CHOUND	15	CHEM./PHYS. THE	4.1.	SOF SET		5 MIDNIGH	4 T E	DUMPING
	6. OTHER (specify).		6. OTHER	(8	pecify):		BIOLOGICAL TREA			<del></del>	6. INCINE		
١Ź			1			+	. WASTE OIL REPRO		· - · ·	·			NOTTOBLEH DRUG
1							SOLVENT RECOVE	PΥ		j)	S. OTHER	( ape	ecity):
1			I		L	_1°	OTHER (Specify):						
1			1							<b>!</b>			
E.	SPECIFY DETAILS	OF!	SHE ACTIVITIES AS			**************************************	MCODY:		E-0-1-0-0-0-0-	<b></b>	ritorio, di alla parti sa sun fulloci		
<u> -</u>	WASTE TVOT				V. WASTE RELATE	t D	INFURMATION						
l	WASTE TYPE												
[	1 UNKNOWN	2	LIQUID [3	50	outo   la si	Lur	'GE   15 00	h\$					
8.	WASTE CHARACTER	RIST	ics		to annual manual distriction of the confidence o				, , ,			•	
i-	TI UNKNOWN	12	CORROSIVE Tala	ıç	NITABLE [] 4 R	A DI	DACTIVE TO H	ιςн	41, 9 6	.; •	TILE		
آ	G TOXIC	]7	REACTIVE   8	1 N	IERT 9 F	L A N	YMABLE.						
,	10. OTHER (specify	=				*****	an et anner "Vern General verein"						
	WASTE CATEGORIE		vailable? Specific	m•	such as mamfests, in								
1		s #	, дрего ореспу П	5		, <b>n</b>	The second secon						
<u> </u>					>		A CONTRACTOR OF THE CONTRACTOR						· · · · · · · · · · · · · · · · · · ·
1 2		unt		e S (i	ire)of waste by cnte	Por		ate 1		-		7.65	
<u> </u>	a. SLUDGE	<del> </del>	b. OIL	-	c. SOLVENTS	ļ., -	d, CHEMICALS		eacour:	1-Q1.	135	1.	( OTHER
^~	OUNT	1	OUNT	4.1		<b></b>		ĺ	:			1	
UN	NIT OF MEASURE	UN	IT OF MEASURE	Ur	NIT OF MEASURE	ψi.	ILY DE MEASURE	į is	1 1 2.	1.15	V = 145 £	10,	AT OF MEASURE
	- ·-	]		١								1	
x'	(1) PAINT.	×	(FIOIL Y	, x	THALOGENATED	·×:		X	Ţ.,,	, <del></del> 	14	'×	LABORATORY
	PIGMENTS		WASTES		SOLVENTS	1	\	ļ	ļ			1	FHAHMACEUT.
	(2) METALS		(210 THER (specify):		121 NON-HALOGNES		121 PICKLING		]	60%	10°		12: HOSPITAL
-	SLUDGES	4						ì				+-	<del> </del>
	(3) POTW				GO OTHER (Specify)		CAP CA US TICS				IG/ (All Higs		SI RADIOACTIVE
	(4) ALUMINUM SLUDGE	1					4: PESTICK ES	1	1	e de la composition della comp			41 MUNICIPAL
<u> </u>	<del> </del>	1				-	<del> </del>		j			ļ	(6) OTHER (specify)
	15) OTHER(specify):					<b> </b>	(B) DYES/INAS	]			CARO S . ZASTES	1	STOLO - HEHISPOCITY)
							(6) CYANICE	<b> </b>	-		,		
							CIPHENOLS						
							IN HALOGENS	7				-	
						-		i				1	
							Carron	-				1	
							TO METALS					1	
							(11) O DIER (*Pecify)					1	
						Γ							

### CROWN CENTRAL PETROLEUM CORPORATION



PRODUCERS • REFINERS • MARKETERS OF PETROLEUM PRODUCTS AND PETROCHEMICALS

GENERAL OFFICES • ONE NORTH CHARLES • P.O. BOX 1168 • BALTIMORE, MARYLAND 21203

June 8, 1981

U.S. EPA Region 4 Sites Notification 345 Courtland Street, N.E. Atlanta, Georgia 30365

Re: SECTION 103 (c)

SUPERFUND NOTIFICATION FORM COMPLIANCE LETTER

Dear Sir:

Crown Central Petroleum Corporation, a refiner and marketer of petroleum products with principal offices in Baltimore, Maryland, hereby submits EPA Form No. 8900-1, Notification of Hazardous Waste Site. Crown owns and operates numerous terminals and service stations in the mid-Atlantic and southeastern United States. To the best of our "knowledge, belief, recollection, and review of reasonably available records," the information contained in our notification form is complete and correct. Crown interprets the statute and implementing regulations to require notification for past disposal activities involving leaded tank bottoms. Supplementary information concerning disposal practices is provided on Attachments A and B.

We have diligently attempted to comply with the superfund notification requirement, considering the short compliance period. As early as February, 1981, we contacted key personnel, conducted meetings, and discussed compliance strategies. Upon the issuance of the notification form and instructions by EPA, Crown immediately notified all company officers of the requirement and prescribed mandatory compliance actions. Compliance was achieved by searching all accessible company files and records in all departments, and by conducting interviews with long-term employees and employees previously or presently involved in hazardous waste activity. We feel that Crown's actions undoubtedly constitute a "good faith" effort to comply with the EPA requirements and the Section 103(c) requirements of the Comprehensive Environmental Response, Compensation, and Liability Act of 1980 (Public Law 96-510).

Sincerely yours,

Edwin P. Mampe

Director,

Regulatory Affairs

EPM/SLK/agh

Attachments

# Notification of Hazardous Waste Site

United States Environmental Protection Agency Washington DC 20460

This initial notification information is required by Section 103(c) of the Comprehensive Environmental Response, Compensation, and Liability Act of 1980 and must be mailed by line 2.3000.

810608

_	be mailed by June 9, 1981.	and must windin approxi		6A500	00 001	031
A	Person Required to Notify:	0-0-	Combuni Do	troleum Cor	noration	
	Enter the name and address of the	ne person			POLACION	
	or organization required to notify	suce 1 Nort	h Charles	<u>Street</u>		<del></del>
		<sub>City</sub> Baltim	ore	State Md.	Zip Code 212	01
В	Site Location:	C	oum Contral	l Petroleum	Corporati	On
	Enter the common name til knov actual location of the site.	Street 27	65 Woodwin		COIPOIRCI	
6	GAD079362	66   CIN Doraville	2 County	'State Ga.	Zrp Code 3034	0
C	Person to Contact:		on dondants	Phil B. (1	Warkoting	X++ornov
	Enter the name, title (if applicable business telephone number of the contact regarding information submitted on this form.	ne person	(301) 539-7		Marketing	——
D	Dates of Waste Handling:					<del></del>
	Enter the years that you estimate freatment, storage, or disposal beended at the site.	e waste egan and From (Year) 1962	Та (Үөэн) 196	53		
	Waste Type: Choose the opti	on your prefer to complete	<u> </u>			***************************************
-	Option I: Select general waste tyou do not know the general waste tyou do not know the general waste encouraged to describe the site.  General Type of Waste: Place an X in the appropriate boxes. The categories listed overlap. Check each applicable category.	ypes and source categories. U ste types or sources, you are	Resource Conse regulations (40 of Specific Type of EPA has assigned in the regulation of the list of hazard contacting the EPA hazard contacting the EPA hazard four the list of hazard contacting the EPA hazard for the List of hazard contacting the EPA hazard for the EPA hazard f		Act (RCRA) Section of the fact of the fact hazardou of RCRA E boxes provided. A second of the fact of	on 3001  us waste  Enter the  copy of
	1. D Organics	1. C Mining	located.			
	2. D Inorganics	2. Construction	K052		7	
	3. D Solvents	3. 🗆 Textiles	Aude		1	
	4. Pesticides	4. 🗆 Fertilizer	· · · · · · · · · · · · · · · · · · ·		1	_
	5.   Heavy metals	5.  Paper/Printing			1	_
	6. 🗆 Acids	6. 🛘 Leather Tanning			1	
	7. 🖸 Bases	7. 🗆 Iron/Steel Foundry			7	
	8. D PCBs	8.   Chemical, General			)	
	<ol><li>Mixed Municipal Waste</li></ol>	9. D Plating/Polishing	-			
	10. 🖾 Unknown	10.  Military/Ammunition		(1) 2	<u> </u>	
	11. Other (Specify)	11.   Electrical Conductors			J 5	
		12.  Transformers		D	ੇ ਨੇ ਕ	
		13. Utility Companies		7	_ ப	0
		14 Sanitary/Refuse	1	5. T.		0
•		15   Photofinish		77.1	<u>6∏</u>	<b>)</b>
	•	16. 🗆 Lab /Hospital	•		<b>5</b> <	21
-		17 Unknown 18 Other (Specify)			CEIVED	Q1
	Lorin Approved OMB No. 2006 0138			+tn .g		4

	Notification of Hazardous Waste Site	Side Two	
	Waste Quantity	Facility Type	Total Facility Waste Amount
	Place an X in the appropriate boxes to	1. 🗆 Piles .	cube feet unknown
	indicate the facility types found at the site.	2. C Land Treatment	galluns
	In the "total facility waste amount" space give the estimated combined quantity	3. 🖸 Landfill 4. 🖸 Tanks	•
	(volume) of hazardous wastes at the site using cubic feet or gallons.	5. D Impoundment	Total Facility Area
	In the "total facility area" space, give the	6. Underground Injection	square free unknown
	estimated area size which the facilities	7 Drums, Above Ground	ecres
	occupy using square feet or acres.	8. Drums, Below Ground	• •
		9 M Other (Specify) burial	<u>pit</u>
•	Known, Suspected or Likely Releases to Place an X in the appropriate boxes to indicate or likely releases of wastes to the environment Note: Items Hand I are optional. Completing	o the Environment: e any known, suspected, it. these items will assist EPA and State a	nd local governments in locating and assessi
	Place an X in the appropriate boxes to indicate or likely releases of wastes to the environment Note: Items Hand I are optional. Completing hazardous waste sites. Although completing	the Environment: e any known, suspected, it. these items will assist EPA and State it the items is not required, you are enco	☐ Known ☐ Suspected ☐ Likely ★★Non ind local governments in locating and assessionaged to do so
	Place an X in the appropriate boxes to indicate or likely releases of wastes to the environment Note: Items Hand I are optional. Completing hazardous waste sites. Although completing Sketch Map of Site Location: (Optional	the Environment: e any known, suspected, it. these items will assist EPA and State it the items is not required, you are enco	nd local governments in locating and assessi
	Place an X in the appropriate boxes to indicate or likely releases of wastes to the environment Note: Items Hand I are optional. Completing hazardous waste sites. Although completing	the Environment: e any known, suspected, it. these items will assist EPA and State it the items is not required, you are enco	nd local governments in locating and assessi
	Place an X in the appropriate boxes to indicate or likely releases of wastes to the environment Note: Items Hand I are optional. Completing hazardous waste sites. Although completing Sketch Map of Site Location: (Optional Sketch a map showing streets, highways, routes or other prominent landmarks near the site. Place an X on the map to indicate	the Environment: e any known, suspected, it. these items will assist EPA and State it the items is not required, you are enco	nd local governments in locating and assessi
	Place an X in the appropriate boxes to indicate or likely releases of wastes to the environment Note: Items Hand I are optional. Completing hazardous waste sites. Although completing Sketch Map of Site Location: (Optional Sketch a map showing streets, highways, routes or other prominent landmarks near the site. Place an X on the map to indicate the site location. Draw an arrow showing the direction north. You may substitute a	the Environment: e any known, suspected, it. these items will assist EPA and State it the items is not required, you are enco	nd local governments in locating and assessi
	Place an X in the appropriate boxes to indicate or likely releases of wastes to the environment Note: Items Hand I are optional. Completing hazardous waste sites. Although completing Sketch Map of Site Location: (Optional Sketch a map showing streets, highways, routes or other prominent landmarks near the site. Place an X on the map to indicate the site location. Draw an arrow showing	the Environment: e any known, suspected, it. these items will assist EPA and State it the items is not required, you are enco	nd local governments in locating and assessi
	Place an X in the appropriate boxes to indicate or likely releases of wastes to the environment Note: Items Hand I are optional. Completing hazardous waste sites. Although completing Sketch Map of Site Location: (Optional Sketch a map showing streets, highways, routes or other prominent landmarks near the site. Place an X on the map to indicate the site location. Draw an arrow showing the direction north. You may substitute a	the Environment: e any known, suspected, it. these items will assist EPA and State it the items is not required, you are enco	nd local governments in locating and assessi
	Place an X in the appropriate boxes to indicate or likely releases of wastes to the environment Note: Items Hand I are optional. Completing hazardous waste sites. Although completing Sketch Map of Site Location: (Optional Sketch a map showing streets, highways, routes or other prominent landmarks near the site. Place an X on the map to indicate the site location. Draw an arrow showing the direction north. You may substitute a	the Environment: e any known, suspected, it. these items will assist EPA and State it the items is not required, you are enco	nd local governments in locating and assessi
1	Place an X in the appropriate boxes to indicate or likely releases of wastes to the environment Note: Items Hand I are optional. Completing hazardous waste sites. Although completing Sketch Map of Site Location: (Optional Sketch a map showing streets, highways, routes or other prominent landmarks near the site. Place an X on the map to indicate the site location. Draw an arrow showing the direction north. You may substitute a	the Environment: e any known, suspected, it. these items will assist EPA and State it the items is not required, you are enco	nd local governments in locating and assess

Description of Site: (Optional)

Describe the history and present

Describe the history and present conditions of the site. Give directions to the site and describe any nearby wells, springs, lakes, or housing, include such information as how waste was disposed and where the waste came from. Provide any other information or comments which may help describe the site conditions.

Disposal occurred at a petroleum product terminal site. Leaded tank bottoms generated by the cleaning of gasoline storage tanks were disposed of onsite by the burial method in accordance with standard industry practice. See attachments A and B for additional information concerning disposal methods. The estimated quantity of waste disposed of at this site cannot be determined. During the latter part of 1962 or the early part of 1963, tank No. 1 was cleaned and two wheelbarrow loads of leaded tank bottoms were buried between tank Nos. 1 and 2. To the best of our knowledge, this site does not pose a threat to the surrounding environment.

J Signature and Title:

The person or authorized representative (such as plant managers, superintendents, trustees or attorneys) of persons required to notify must sign the form and provide a mailing address (if different than address in item A). For other persons providing notification, the signature is optional. Check the boxes which best describe the relationship to the site of the person required to notify. If you are not required to notify check "Other"

-119	GIIVILOIMIGIICI	
<del>;</del>	Edwin P. Mampe	-
Name	Director, Regulatory Affair	S Owner, Present
Street	1 North Charles Street	☐ Owner, Past ☐ Transporter
City	Baltimore State Md. Zup Code 21201	Operator, Present Operator, Past
Signati	Mamphone June 8.	☐ Other

[FR Doc. 81-11500 Filed 4-14-81; 8:45 am] BILLING CODE 8540-29-C

#### ATTACHMENT A

#### SUPPLEMENT TO EPA FORM NO. 8900-1

### STANDARD INDUSTRY PRACTICES FOR THE DISPOSAL OF LEADED TANK BOTTOMS

The petroleum industry has been aware of the dangers associated with the removal of leaded sludges from gasoline storage tanks for the past fifty years. Preventative measures have been followed to afford protection to the environment and to workers.

Prior to the enactment of health and environmental legislation such as the Resource Conservation and Recovery Act (RCRA), the American Petroleum Institute (API) issued guidelines and procedures (API Publications RP2015 and RP 2015A) to ensure that adequate safety, health, and environmental precautions were undertaken by the petroleum industry during tank cleaning and sludge disposal operations. These guidelines prescribed appropriate (i) personal protective equipment, (ii) tank entry and inspection standards, (iii) use of lead-in-air analyzers and sampling techniques, and (iv) methods for sludge disposal.

API recommended two methods for sludge disposal - weathering and burial. Sludges disposed of by the weathering technique involved the spreading of the sludge on a ground, grass, or concrete surface in a layer approximately three inches thick. The sludge was spread in a location accessible to air flow and sunlight. The area was then secured to prohibit entry. Laboratory tests indicated that when exposed to the elements the organic lead compounds contained in sludges decompose into inorganic lead compounds without creating air, soil, or water contamination problems. Within four weeks, the enclosed area usually contained less than 20 parts per million of organic lead. Soil tests were recommended to verify these levels and

the area was then declared free of any lead hazard. A study compiled by the Ethyl Corporation concludes that the weathering technique was a safe method of handling sludges and that sludges weathered for four weeks usually contain less than 1 part per million of organic lead. See Attachment B for additional analytical data concerning this study.

The second method for disposal involved the burying of sludges in a pit covered with one to two feet of fresh earth. The burial areas were clearly marked to prevent future unearthings, since lead compounds in buried sludges would decompose much more slowly than those sludges treated by weathering. Generally, the standard industry practice was to allow the sludge to weather in an open pit for a period of two to three weeks before covering to reduce organic lead content. These burial pits were generally located within the confines of the tank farm area away from worker activity.

Crown Central Petroleum Corporation has not engaged in any on-site leaded sludge disposal activity for at least five years. Also, there are no known instances where service station sludges were buried on-site. All Crown-operated marketing facilities are currently in compliance with RCRA and dispose of sludges at approved off-site waste treatment facilities.

#### ATTACHMENT B

#### METHODS OF DISPOSING OF SLUDGE FROM LEADED GASOLINE STORAGE TANKS

H. K. BALL

ETHYL CORPORATION

#### RELEASE AFTERNOON PAPERS TUESDAY, MAY 14

### METHODS OF DISPOSING OF SLUDGE FROM LEADED GASOLINE STORAGE TANKS †

#### H. K. BALL\*

#### ABSTRACT

For many years sludge from leaded gasoline storage tanks has been successfully disposed of by burial. Recently, inquiries have been received from a number of oil companies asking for an alternate method of sludge disposal. Available space for sludge pits is being exhausted, and in some areas high water tables offer disposal problems.

Various methods of sludge disposal were studied, including roasting, chemical treatment, leaching, etc. These methods, although effective, all have drawbacks.

Since the early 1930's, the potential toxicity of sludge from leaded gasoline storage tanks has been recognized. Therefore, it has been necessary to dispose of sludge by a method which would avoid harmful effects both from skin contact or inhalation of its vapors. Burial met these requirements.

In recent years, however, an increasing number of inquiries have been received from oil companies asking for an alternate method of sludge disposal because available space for sludge pits is being exhausted and in some areas high water tables create disposal problems.

In looking for alternate methods of sludge disposal, the basic requirements could be defined as follows:

- 1. Sludge should be reduced in the least possible, time to a nonhazardous condition.
- 2. The method should be economical and should apply to tanks in all areas—refinery, terminal, bulk storage, etc.
- 3. The method should require no particular skill or technical assistance to perform it safely.

Possible methods for disposing of sludge were considered as follows:

- 1. Chemical Methods (applied after removing sludge from tank)
  - a. Aqueous potassium permanganate.
  - b. Sodium hypochlorite.
  - c. Chlorine in acetic acid.
  - d. Iodine solution.
- 2. Thermal Methods
- a. Ignition: Place a thin layer of sludge into a shallow but long and wide trench, cover with kerosine, and ignite with a torch. The heating must be for a sufficiently long period of time to vaporize all liquid from the sludge and heat the dried mass to approximately 150 C.
- b. Roasting: Place contaminated sludge on a large steel plate and heat with a flame to 150 C to 200 C. Heating may be applied in any manner.

\*Ethyl Corp., New York, N. Y.
† Presented to a session on operating practices during the
28th Midyear Meeting of the American Petroleum Institute's
Division of Refining, in the Benjamin Franklin Batel, Philadelphia, Pa., May 14, 1963; presiding, W. T. Askew, Sun Oil Co.,
Philadelphia, Pa.

It was learned that the tetraethyllead would dissipate after spreading leaded sludge in a 3-in. layer. From tests that have been conducted to date, it appears that a weathering period of 30 days is adequate to reduce most sludges to a lead level of below 20 ppm, which is considered safe. Factors such as freezing weather could extend this period somewhat depending upon conditions.

Data are still being accumulated to further support

- 3. Physical Methods (Weathering Sludge): Spread sludge in a thin layer and allow exposure to the elements.
- 4. Combination of Preceding Methods: Weathering followed by ignition or roasting.
- 5. Miscellaneous Methods: A host of other chemical decontaminants such as sulfuryl chloride in kerosine, hydrochloric acid, hydrogen peroxide, etc. were rejected because of secondary problems associated with use of these decontaminants.

Decontamination of sludge prior to removal from the gasoline storage tank (chlorine in the water wash) was rejected because of corrosion problems.

#### Advantages and Disadvantages of Various Methods

In the course of our investigations, it was agreed that:

- 1. Decontaminating sludge with chemicals (chlorine in acetic acid, iodine in potassium iodide solution, bleach, and potassium permanganate) is only partially effective and quite expensive. The chemicals react with other components of gasoline tank sludge and lose some of their effectiveness. Thorough mixing is essential for proper contact. This method is not considered feasible because of the difficulty of producing intimate contact of chemicals with sludge, the possible hazards of handling the chemicals, their cost, manpower requirements, and special equipment that may be required.
- 2. The most effective methods for decontaminating gasoline storage tank sludge are "thermal methods." Heating sludge to 200 C for 20 min after all moisture is removed reduces the tetraethyllead (TEL) content down to 0.00002 percent by weight. Heating may be carried out in a number of ways. However, the "thermal method" is only applicable when special facilities are available. The method may well require the removal of the sludge to a remote location involving rehandling of the material. Except under special circumstances, the economics do not appear good.

	•		

3. Spreading sludge in a thin er on the ground and allowing it to "weather" has in proven an effective procedure for decontaminating sludge. Tests show that under Gulf Coast weather conditions, this method was superior to chemical treatment. This also proved true in mid-Continent area tests. In colder parts of the country weathering may be less effective as the sludge is in an inactive state because of low temperatures. However, as the weather moderates the weathering will continue.

#### Chemical Methods

The chemical methods were tested by removing portions (125 g each) from a large sludge sample and analyzing for TEL before and after treatment by methods shown in Table 1. The results from this test (Table 1) demonstrate that treating with halogens (which react instantly when in contact with TEL), potassium permanganate, and bleach considerably reduces the TEL content. However, in no case did the decontaminants remove all TEL.

A secondary problem presented itself in that all chemical decontaminants reacted with other components of sludge, presumably iron in its lower state of oxidation and organic petroleum compounds. This tends to use up the decontaminant.

Mixing sludge with chemical decontaminants appears to be necessary to improve contact with TEL. When potassium permanganate crystals were placed on the surface of sludge contained in a glass vessel, solution and diffusion of permanganate was extremely slow and not complete. Furthermore, the dilute permanganate solution was reduced by impurities in sludge more rapidly than it reacted with TEL.

Further tests to decontaminate sludge with potassium permanganate (1 lb permanganate to 99 lb sludge) proved unsuccessful. Even after stirring for 1 hr the TEL content was only reduced to 0.0022 percent by weight. Also, all potassium permanganate was reduced by this particular sludge sample. Based upon a cost of potassium permanganate at 26 cents per pound, this method appears to be quite expensive (approximately \$8.50 per cubic yard of sludge for permanganate only. The equipment and labor costs would be even higher).

TABLE 1-Decontamination by Chemicals of Gasoline Storage Tank Sludge

Decontaminant	Active Part of Decontaminant, 1 Part to 99 Parts Sludge (Weight)	Contact Time	Unreacted TEL Percent of Sludge (Weight)
None (control sample)	•••	•••	0.0120
acetic acid  Iodine-potassium	Chlorine	3	0.0022
iodide	Iodine	3	0.0006
Potassium permanganate	Permanganate	3	0.0023*
Bleach	Bleach	3	0.0049

 $<sup>^{\</sup>circ}$  Constant stirring of a similar mixture for 1 hr resulted in a value of 0.0022 percent.

The addition of Coercent by weight TEL to a single sample of sluce originally containing approximately 0.01 percent by weight TEL was readily decontaminated with chlorine in acetic acid to 0.0025 percent by weight of TEL. Apparently, TEL added to sludge is easy to decontaminate whereas TEL originally present in sludge is more difficult to decontaminate.

#### Thermal Methods

Thermal methods of roasting and ignition were tested and found to be effective, especially the former. A 300-g sample of sludge and a 2-lb sample of sludge were placed into steel trays and heated for 1 hr and 20 min. The temperature of the sludge remained below 100 C for the first hour (because of water on the sludge). During the next 20 min the temperature increased to 150 C on the surface and 200 C on the bottom layer.

The TEL content dropped to 0.00001 and 0.00002 percent by weight, respectively. This treatment appeared to be very promising because TEL and all other organic lead compounds are completely destroyed by heating.

The ignition method was tested by placing a 1-in. layer of wet sludge • in a tray and covering it with a thin layer of kerosine. The kerosine was then ignited. A relatively large volume of kerosine (1 volume kerosine to 4 volumes sludge) was needed to volatilize the moisture and reduce the TEL content to 0.0002 percent by weight. Two additions of kerosine were required to remove the moisture, and a third addition was necessary to increase the temperature of the sludge to a maximum of 145 C.

Burning air-dried sludge \* with a kerosine and oil mixture reduced the TEL content to 0.00003 percent by weight. The use of kerosine only is not very satisfactory when using a deep bed of sludge (2 in.). Kerosine liquid and vapor prevent a rapid rise in the temperature of the sludge. The sludge bed acts as a wick, and if the temperature of the combustible vapor is not great enough, thermal decomposition of TEL is very slow. The use of a fuel with a higher boiling point is more effective for increasing the temperature of the sludge. For this reason, heating sludge with a flame or "roasting" is preferable to heating with a volatile solvent. The TEL content of a flame-heated sludge \* sample (overhead flame) dropped to 0.00001 percent by weight.

#### Sludge-Weathering Method

In 1955 the Ethyl Corporation started a series of field tests involving the cleaning of leaded gasoline storage tanks. We were interested in what might be the maximum exposure hazard of lead vapors to personnel in a tank having contained leaded gasoline, and we were also interested in the nature of the sludge being removed from a tank. As a part of our study, sludge samples were sent to our chemical research and development laboratory in Baton Rouge for analysis. Sludge in glass bottles, standing in the laboratory before being analyzed, was found to stratify in layers composed of solids, gasoline, and water. It was further found that by centrifuging these samples, the TEL in the sludge can be removed.

<sup>\* 0.012</sup> percent by weight TEL.

As a matter of passing interest, e of this material was put in the sunlight and it found that TEL diffused into the atmosphere. Further checking by the laboratory group showed that the level of lead in sludge exposed to the elements (with or without the sun being present) rapidly declined.

For this "weathering" process to be a satisfactory method of decontaminating sludge two questions had to be answered.

1. How low did the level have to be reduced to make the sludge safe?

#### 2. How long would it take?

To answer the first of these it was reasoned that the sludge is safe if it will not contaminate the air above it. Tests were then made to see what the LIA (lead-in-air) values were in the air above "weathering" sludge. The results showed that the values are low at all times, even with no apparent wind. This meant that the sludge, as far as air contamination is concerned, is essentially safe as soon as it is spread in the open. To be on the safe side, however, Ethyl Corporation has set a figure at 20 ppm of organic lead as the limit in the




FIG. 1-One-Inch-Thick Sludge Weathered on Ground.




FIG. 2—Two-Inch-Thick Sludge Weathered on Ground.

sludge that can be cr dered safe in the open air after it has been "weatheress"

In the early studies, sludge levels of various thicknesses were tried over a period of time. These are shown in Fig. 1 through Fig. 4. In addition to placing these on the ground, some were placed on steel plate with no apparent difference. These were small-scale tests.

Following this, full-scale tests were carried out at tank cleanings, two of which are shown in Tables 2 and 3.

The LIA values remained almost constant for the duration of both tests even though the lead content of the sludge was disappearing (Table 3).

From the LIA data, it was concluded that there is no danger of inhaling a harmful quantity of lead, provided there is nothing to restrict normal air movement.

The lead content of the sludge in about 3 weeks time dropped 90 percent or more in the 4-in-thick patches (Fig. 3) and 98 percent or more in the 2-in.-thick patches (Fig. 2).

Based on data such as this, it was decided that it would be entirely satisfactory to dispose of the con-




FIG. 3—Four-Inch-Thick Sludge Weathered on Ground.




FIG. 4-Two-Inch-Thick Sludge Weathered on Steel Plate.

tamination in sludge by weathering for a period of 30 days.

As this program continues, considerably more data is being accumulated to substantiate our findings. To date all data obtained has proved our original conclusions to be correct.

The following procedure was developed for disposal of sludge so that a uniform method would be followed in arriving at a satisfactory completion of a sludge-weathering program:

#### 1. Location of disposal area:

- a. The site selected for sludge disposal should be in a remote part of the property and within property limits where it can be fenced off from the public. It should be located away from buildings. If the sludge is spread near the tank being cleaned, it should be outside the surrounding firewall, so that the possibility of gasoline vapors affecting the tank cleaning operations will be eliminated.
- b. The disposal area should be located so that personnel working in, on, or around the tank will not get into the spread-out sludge.
  - c. It can be a bare ground, grass, or concrete surface.
    d. It must be fairly smooth and well drained so that
- water will not stand on it.
- e. The total area, whether in one or several patches, must be sufficiently large to permit spreading the sludge

TABLE 2-Typical Weathering Results

TEL Content in Sludge

Weathering	in Parts P	er million
Time (Days)	Two-Inch- Thick Patch	Four-Inch- Thick Patch
Ú	38.0	48.0
5	2.9	10.6
8	1.1	2.3
17	0.7	2.0
24	0.6	0.7
31	0.5	0.3

TABLE 3-Typical Lead-in-Air Readings

Micrograms TEL per Cubic Foot of Air

Weathering	Cubic ro	Ot OI AIF
Time	Three Inches	Waist Level
(Days)	Above Sludge	Above Sludge
1	1	1
2	1	1
5	1	1

in a layer not over 3 in. thick. The total area required will, of course, be determined by the amount of sludge in the tank.

- f. It should be so located that air can circulate freely over the surface of the sludge. Exposure to the sun is desirable but not mandatory.
- 2. Remove sludge from the tank in the usual manner following the safety recommendations approved by the American Petroleum Institute.

- 3. The sludge can be moved from the tank to the spreading area in available plant equipment. Wheelbarrows, buckets, or other small containers may be used for moving it a short distance. Dump trucks, lugger buckets, etc. may be used for longer distances. The containers used should be metal. After use, they should be washed thoroughly with water.
- 4. The sludge can be spread with hoes, rakes, or shovels. It should be spread as uniformly as possible to a maximum thickness of 3 in. If the area permits it, a thinner spreading is desirable.
- 5. Personnel who handle and spread the sludge should be dressed in special clothing as recommended for tank cleaning. Masks will not usually be necessary unless there is no air movement and vapors can be detected by odor at face level.
- 6. After the spreading is completed the sludge patch or patches should be roped off and marked so that no one will walk through or stand in the sludge.
- 7. The spread sludge should be left for at least four weeks. After that it may be treated as any other non-toxic waste material. It is satisfactory to remove signs, fences, etc. and leave the sludge in the preselected area permanently. The four-week weathering period applies when the ambient temperature is above 32 F. Therefore, if temperatures under 32 F exist during the period of weathering, this period of subfreezing temperatures should not be included in the recommended four weeks of weathering.
- 8. Whenever the weathered sludge analyzes 0.002 percent by weight (20 ppm) organic lead or less, it may be considered safe and the sludge may then be treated as any other nonhazardous waste material.

To date we have examined over 100 weathered samples taken from tank cleanings and have definite results on 38. These weathered satisfactorily, the organic lead being reduced to less than 20 ppm. A number of samples had to be ruled out because we had no base line to start with, although we have reason to believe that these did weather satisfactorily.

This unquestionably is a radical departure from the early and original method of sludge burial. The new method was brought about by necessity; and, very fortunately, because of the curiosity of our people in our chemical research and development laboratories, we were able to bring to the field a method that, judging from figures received to date, is going to solve a lot of our sludge problems.

We are preparing a more detailed paper on some of the intricacies involved which, hopefully, should be published in several months.

#### ACKNOWLEDGMENT

The author wishes to acknowledge the assistance of Mr. Louis J. Snyder of the chemical research and development department of Ethyl Corporation who is responsible for directing the laboratory work which was done in connection with this study.

## sludge disposal

One of two methods is commonly used for disposing of sludge from leaded-gasoline storage tanks. They are "burying" or "weathering". Both methods are recognized by API RP-2015. There are other effective methods, such as "thermal" methods, but they are not commonly used because special facilities are required.

BURYING—In this method a pit is dug either manually or by bulldozer. The sludge is dumped into the pit and then covered with 1 to 2 feet of fresh earth. This area should be adequately marked so that no one inadvertently uncovers the buried sludge. Experience indicates that buried organic lead compounds decompose very slowly to inorganic materials. If a ditch or trench is dug through the sludge pit, organic lead compounds may be uncovered.

WEATHERING - This method is safe, effective, and economical. Laboratory tests show that organic lead compounds in sludge when exposed to the elements will decompose to inorganic lead compounds. Laboratory and field tests show that if the procedures, as outlined in this section are followed, there will be no special air, soil, or water contamination problem. The basis for this is: (1) The total quantity of organic lead in a sludge weathering bed is small. Concentrations rarely exceed the normal range of 0.1 to 0.4 pounds organic lead per ton of sludge. (2) Regardless of the concentrations or total quantity of lead in the sludge weathering bed, the amount of organic lead exposed to the atmosphere at the surface of the weathering bed is very small. Lead-in-air tests taken over or immediately downwind of the weathering bed indicate that lead-in-air concentrations do not exceed the threshold limit value for organic lead. This indicates the atmosphere in the area is essentially safe from an occupational health hazard standpoint as soon as the sludge is spread. (3) Organic lead compounds are dissolved in the gasoline hydrocarbon fractions of the sludge and do not migrate into water or soil. Thus, the physical properties of organic lead in sludge in the weathering beds are such that vaporization, absorption in water or soil do not constitute a health problem.



ETHYL CORPORATION
PETROLEUM CHEMICALS DIVISION

"WEATHERING" PROCEDURE FOR DISPOSAL OF SLUDGE FROM LEADED GASOLINE STORAGE TANKS

- 1. Location of disposal area:
  - a. The site selected for sludge disposal should be in a remote part of the tank owners property and within property limits where it can be fenced off from the public. It should be located away from buildings. If the sludge is spread near the tank being cleaned, it should be outside the surrounding firewall, so that the possibility of gasoline vapors affecting the tank cleaning operations will be eliminated.
  - The disposal area should be located so that personnel working in, on, or around the tank will not get into the spreadout sludge.
  - c. It can be a bare ground, grass or concrete surface.
  - d. It must be fairly smooth and well drained so that water will not stand on it.
  - e. The total area, whether in one or several patches, must be sufficiently large to permit spreading the sludge in a layer not over 3" thick. The total area required will, of course, be determined by the amount of sludge in the tank.
  - f. It should be so located that air can circulate freely over the surface of the sludge. Exposure to the sun is desirable but not mandatory.
- Remove sludge from the tank in the usual manner following the safety recommendations approved by API.
- 3. The sludge can be moved from the tank to the spreading area in available plant equipment. Wheelbarrows, buckets or other small containers may be used for moving it a short distance. Dump trucks, lugger buckets, etc., may be used for longer distances. The containers used should be metal. After use, they should be washed thoroughly with water.
- 4. The sludge can be spread with hoes, rakes or shovels. It should be spread as uniformly as possible to a maximum thickness of three inches. If the area permits it, a thinner spreading is desirable.
- Personnel handling and spreading the studge should be dressed in special clothing as recommended for tank cleaning. Normally, masks will not be necessary if there is air movement.
- 6. After the spreading is completed the sludge patch or patches should be roped off and marked so that no one will walk through or stand in the sludge.
- 7. While sludge will normally weather within four weeks when the sludge temperature is above 32 degrees F, lead-in-sludge tests should be made before declaring it a nontoxic waste material. The number of days during which sludge temperatures are 32 degrees F or lower should be excluded from the four-week weathering period. If after the four-week weathering period the organic lead content is 20 parts per million or less, 0.002 weight percent, the sludge may then be treated as any other nontoxic waste material. It is then satisfactory to remove signs and fences. The sludge should remain in the preselected area.



#### **FRS Facility Detail Report**




#### **CROWN CENTRAL PETROLEUM CORPORATION**

2765 WOODWIN DRIVE DORAVILLE, GA 30360-3119 <u>EPA Registry Id</u>: 110001389417 Facilty Registry Service Links

- Search
  - O FRS Facility Query
    O FRS EZ Search
  - O FRS EZ Search
- Organization Search
   FRS Physical Data Model
- FRS Geospatial Model
- Contact Us
- Facility Registry Service (FRS)





#### Legend

- Selected Facility
- EPA Facility of Interest
- State/Tribe Facility of Interest

The facility locations displayed come from the FRS Spatial Coordinates tables. They are the best representative locations for the displayed facilities based on the accuracy of the collection method and quality assurance checks performed against each location. The North American Datum of 1983 is used to display all coordinates.

#### **Environmental Interests**

Information System	Information System	Environmental Interest Type	Data	Last Updated	Supplemental Environmental Interests:
	<b>I</b> Ω		Source	Date	
RESOURCE CONSERVATION AND RECOVERY ACT	GAD079362661	UNSPECIFIED UNIVERSE (N)	RCRAINFO	09/02/2000	
<u>INFORMATION SYSTEM</u>					
AIR FACILITY SYSTEM	1308900140	AIR SYNTHETIC MINOR (N)	AIRS/AFS	03/04/2011	
GEORGIA - GEOGRAPHIC ENVIRONMENTAL INFORMATION	440549	STATE MASTER	GEIMS		UST-1
MANAGEMENT SYSTEM					UNDERGROUND STORAGE TANK
					PROGRAM
					UST-2
			!		UNDERGROUND STORAGE TANK
					PROGRA <b>M</b>
					UST-3
					UNDERGROUND STORAGE TANK
					PROGRAM
NATIONAL EMISSIONS INVENTORY	NEIGA0890140	CRITERIA AND HAZARDOUS AIR POLLUTANT	NEI		
		INVENTORY			1

Additional EPA Reports: MyEnvironment Enforcement and Compliance Site Demographics Watershed Report

Standard Industrial Classification Codes (SIC)

National Industry Classification System Codes (NAICS)

Data Source	SIC Code	Description	Primary	Data Source	NAICS Code	Description	Primary
AIRS/AFS	5171	PETROLEUM BULK STATIONS AND TERMINALS		RCRAINFO	42271		
		Facility Codes and Flags			Facility Mailing Adv	dracese	<del></del>

EPA Region:04	Affiliation Type	Delivery Point	City Name	State	Postal Code	Information System
Duns Number:	REGULATORY CONTACT	P O BOX 47279	DORAVILLE	GA	30362	RCRAINFO
Congressional District Number: 06	FACILITY MAILING ADDRESS	P O BOX 47279	DORAVILLE	GA	30362	RCRAINFO
Legislative District Number: DM	OWNER	1 N CHARLES ST	BALTIMORE	MD	21201	GEIMS
HUC Code/Watershed: 03130001 / UPPER CHATTAHOOCHEE	FACILITY MAILING ADDRESS	1 N CHARLES ST	BALTIMORE	MD	21201	GEIMS
US Mexico Border Indicator:	OPERATOR	PO BOX 1168	BALTIMORE	MD	21203	GEIMS
Federal Facility: NO	OWNER	1 N CHARLES ST	BALTIMORE	MD	2120	GEIMS
		l	1	1		

	<u>Tribal Land:</u> NO				FACILITY MAILING ADDRE	ESS P O BOX 47279	DORAVILLE	GA 30362	AIRS/AFS
	Alternati			OPERATOR	PO BOX 1168	BALTIMORE	MD 2120	GEIMS	
			· · · · · · · · · · · · · · · · · · ·		_	Cor	itacts		
Alternative Name		So	urce of Data						
CROWN CENTR	RAL PETROLEUM CORP - DO	RAVILLE	AIR VOLUNTARY	SUBMISSION	Affiliation Type	Full Name	Office Phone	Information System	Mailing Address
CROWN C	ENTRAL PETROLEUM DORA	/ILL	GEIN	AS	REGULATORY CONTACT	OSCAR RAINEY	4044589116	RCRAINFO	⊻iew
CROWN	CENTRAL PETROLEUM COR	P	AIRS/A	AFS	OWNER		410539-7400	GEIMS	View
	Organi	zations							
					OPERATOR		410-539-7400	GEIMS	View
Affiliation Type	Name	DUNS	Information	Mailing	1				
		Number	System	Address	COMPLIANCE CONTACT	PAUL MICHAELSON	4044589116	AIRS/AFS	
OPERATOR	CROWN CENTRAL		GEIMS	View					
	PETROLEUM			İ					
OWNER/OPERATOR	<b>X</b>	079362661	AIRS/AFS						
OWNER	CROWN CENTRAL		GEIMS	View					
	PETROLEUM								





Since 1999, the premier environmental enforcement and complia analysis and reporting resource for government agencies



Multimedia

CWA

SDWA

RCRA

Federal Cases

Watch List

State Framework

#### **Detailed Facility Report**

For Public Release - Unrestricted Dissemination Report Generated on 09/03/2013

US Environmental Protection Agency - Office of Enforcement and Compliance Assurance

Gray text in this report indicates information that is not required to be reported to EPA. These data, typically regarding non-major or smaller facilities, are often incomplete

#### **Facility Permits and Identifiers**

Data Dictionary

Statute	System	Source ID	Facility Name	Street Address	City	State	Zip
	FRS	110001389417	CROWN CENTRAL PETROLEUM CORPORATION	2765 WOODWIN DRIVE	DORAVILLE	GA	30360
€AA .	AFS	1308900140	CROWN CENTRAL PETROLEUM CORP	2765 WOODWIN DRIVE	DORAVILLE	GA	30340
RCRA	RCR	GAD079362661	CROWN CENTRAL PETROLEUM CORP	2765 WOODWIN RD	DORAVILLE	GA	30360

#### **Facility Characteristics**

Data Dictionary

Statute	Source ID	Universe	Status	Areas	Permit Expiration Date	Latitude/ Longitude	Indian Country?	SIC Codes	NAICS Codes
	110001389417					LRT: 33.917473 , -84.275787	No		
CAA	1308900140	Synthetic Minor (Fed. Rep.)	Permanently Closed	SIP , NSPS			NA	5171 5171	
RCRA	GAD079362661		Inactive				No	5171	42271

For the RCRA program, activities that contribute to an overall facility status of Active are displayed in parentheses using the acronym HPACS, where H indicates handler activities, P - permitting, A - corrective action, C convener, and S - state-specific. More information is available in the Data Dictionary.

#### Inspection and Enforcement Summary Data

**Data Dictionary** 

Statute	Source ID	Insp. Last 05Yrs	Date of Last Inspection	Formal Enf Act Last 05 Yrs	Penatties Last 05 Yrs
CAA	1308900140	0	Never	0	\$00
RCRA	GAD079362661	0	05/19/1998	0	\$00

#### Compliance Monitoring History (05 years )

Data Dictionary

Statute	Source ID	System	Inspection Type	Lead Agency	Date	Finding	
- No data records retur	rned.						$\neg$

Entries in italics are not considered inspections in official counts.

#### **Compliance Summary Data**

Data Dictionary

information on the nature of alleged violations is available on the FAQ page

Statute	Source ID	Current SNC/HPV?	Description	Current As Of	Qtrs in NC (of 12)	
CAA	1308900140	NO		08/19/2013		ш
RCRA	GAD079362661	No		08/09/2013	0	

#### Three Year Compliance Status by Quarter

Data Dictionary

Violations shown in a given quarter do not necessarily span the entire 3 months. Information on the nature of <u>alleged violations</u> is available on the FAQ page, and information on the duration of non-compliance is available at the end of this report.

	AIR Compliance Status											
Statute Source ID CAA, 1308900140	QTR1 Oct-Dec10	QTR2 Jan-Mar11	QTR3 Apr-Jun11	QTR4 Jul-Sep11	QTR5 Oct-Dec11	QTR6 Jan-Mar12	QTR7 Apr-Jun12	QTR8 Jul-Sep12	QTR9 Oct-Dec12	QTR10 Jan-Mar13	QTR11 Apr-Jun13	QTR12 Jul-Sep13
HPV History												
Program/Pollutant in Cur	rent Violation											
SIP	TI											
NSPS				1								

High Priority Violator (HPV) History section. "Unaddr" means the facility has not yet been addressed with a formal enforcement action. "Addrs" means the facility has been addressed with a formal enforcement action, but is violations have not been resolved. Lead Agency designated can be US EPA, State, Both, or No Lead Determined. If HPV History is blank, then the facility was not a High Priority Violator. V=Violation: S=Compliance Schedule

	RCRA Compliance Status											
Statute:Source ID RCRA: GAD079362661		QTR1 Oct-Dec10				QTR5 Oct-Dec11		QTR7 Apr-Jun12				QTR12 Jul-Sep13
Facility Level Status												
Type of Violation	Agency											

The first date displayed for a RCRA Violation corresponds to the violation determination date, and the next to the resolution date (if the violation has been resolved).

#### Notices of Violation or Informal Enforcement - AFS, PCS, ICIS-NPDES, RCRAInfo (05 year history)

Data Dictionary

Statute	Source ID	Type of Action	Lead Agency	Date						
	- No data records returned.									

#### Formal Enforcement Actions - (05 year history)

AFS, PCS, RCRAInfo, NCDB

**Bata Dictionary** 

0, . 00,										
Statute	Source ID	Type of Action	Lead Agency	Date	Penalty	Penalty Description				
	- No data records returned.									

In some cases, formal enforcement actions may be entered both at the initiation and final stages of the action. These may appear more than once above. Entries in italics are not "formal" actions under the PCS definitions but are either the initiation of an action or penalties assessed as a result of a previous action. This section includes US EPA and State formal enforcement actions under CAA, CWA and RCRA

ICIS State Dictionary

Primary Law/Section	Case Number	Case Type	Lead Agency	Case Name	Issued/Filed Date	Settlement Date	Federal Penalty	State/Local Penalty	SEP Cost	Comp Action Cost
	- No data records returned.									

Federal enforcement actions and penalties shown in this section are from the integrated Compliance Information System (ICIS-FE&C). These actions may duplicate records in the Formal Enforcement Actions section

#### TRI History of Reported Chemicals Released in Pounds per Year at Site:

Data Dictionary

Year /	Total Air Emissions	Surface Water Discharges	Underground Injections	Releases to Land	Total On-site Releases	Total Off-site Transfers	Total Releases and Transfers
- No da	ta records returned.						

#### TRI Total Releases and Transfers by Chemical and Year

- No data records returned.

#### Demographic Profile of Surrounding Area (3 Miles)

Date Dictionary

Open more detailed information in a new window (links feave OTIS): 1.M; 2.M or 5.M).
This section provides demographic information regarding the community surrounding the facility. OTIS compliance data alone are not sufficient to determine whether violations at a particular facility had negative impacts on public health or the environment. Statistics are based upon the 2000 US Census data, and are accurate to the extent that the facility latitude and longitude listed below are correct. The latitude and longitude are obtained from the EPA Locational Reference Table(LRT) when available.

Radius of Area:	3 Miles	Land Area:	99.36%	Households in area:	32,266
Center Latitude:	33.917371	Water Area:	0.64%	Housing units in area:	33,615
Center Longitude:	-84.275864	Population Density:	2949.15/sq. mi.	Households On Public Assistance:	484
Total Persons:	82,812	Percent Minority:	55.13%	Persons Below Poverty Level:	9,597

Race Breakdown	Persons (%)	Age Breakdown:	Persons (%)
White:	46,762 (56.47%)	Child 5 years and less:	6,770 ( 8.18%)
African-american:	14,940 (18.04%)	Minors 17 years and younger:	17.186 (20.75%)
Hispanic-Origin:	20,788 (25.10%)	Adults 18 years and older:	65,622 (79.24%)
Asian/Pacific Islander:	8,088 (9.77%)	Seniors 65 years and older:	6,598 (7.97%)
American Indian:	541 ( 0.65%)		
Other/Multiracial:	9,339 (11.28%)		


	Education Level (Persons 25 & older)	Persons (%)	Income Breakdown:	Households (%)
	Less than 9th grade:	4,609 ( 8.98%)	Less than \$15,000:	3,055 (9.47%)
1	9th-12th grades:	5,080 ( 9.89%)	\$15,000-\$25,000:	3,221 ( 9.98%)
	High School Diploma:	9,735 (18.96%)	\$25,000-\$50,000:	10,287 (31.88%)
	Some College/2-yr:	10.714 (20.86%)	\$50,000-\$75,000:	6,601 (20.46%)
	B.S./B.A. or more:	21,215 (41,31%)	Greater than \$75,000:	9,008 (27.92%)

Notice About Duration of Violations -- The duration of violations shown on this report is an estimate of the actual duration of the violations that might be alleged or later determined in a legal proceeding For example, the start date of the violation as shown in the ECHO database is normally when the government first became aware of the violation, not the first date that the violation occurred, and the facility may have corrected the violation before the end date shown. In some situations, violations may have been corrected by the facility, but EPA or the State has not verified the correction of these violations. In other situations, EPA does not remove the violation flag until an enforcement action has been resolved.



This report was generated by the Integrated Data for Enforcement Analysis (IDEA) system, which updates its information from program databases monthly. The data were last updated: AFS: 08/19/2013. RCRAInfo: 08/09/2013. FRS: 08/11/2013.

Some regulated facilities have expressed an interest in explaining data shown in the Detailed Facility Reports in ECHO. Please check company web sites for such explanations





Data Quality Information | Contact Us | Privacy & Security Notice | Home

Last updated on September 3rd, 2013